## **Woodturning Shapes**



Tools Used 1 2 5
This is turned in two pieces. It is hollowed from the top with a "disguised" close fitting joint of the collar.



FLAT BOTTLE
Tools Used 1 3 4



Tools Used 1 2 3 5
A wide open top makes these forms easier to hollow out.




Tools Used 1 2 4
This is turned in two pieces. It is hollowed from the top with a "disguised" close fitting joint of the collar




VASE Tools Used 1 2 3 5



RIMMED BOWL
Tools Used 1



LIDDED CONTAINER
Tools Used 1 2 5



VASE Tools Used 1 2 5



VASE Tools Used 1 2 5



THIN WALLED BOWL Tools Used 1



BOTTLE Tools Used 1 2 5



VASE Tools Used 1 2 3 5

## **Woodturning Shapes (Cont'd.)**



VASE
Tools Used 1 2 3 5
A wide open top makes these forms easier to hollow out.



Tools Used 1 3 5
This form would follow the same steps as making a box – but larger.



THIN WALLED OPEN BOWL
Tools Used 1



JAR Tools Used 1 2 5



BOTTLE Tools Used 1 4 5



VASE Tools Used 1 3 5



CLOSED FORM
Tools Used 1 2 5



FOOTED DISH
Tools Used 1



OPEN BOWL Tools Used 1



HOLLOW FORM

Tools Used 1 2 5

This shape can be hollowed out with a normal scraper because of the wider opening.



LONG NECKED BOTTLE

Tools Used 1 2 4 5

Turned in 2 pieces with disguised join at the bottom of the neck.



SPHERICAL VASE
Tools Used 1 2 3 5